



Manual test stand for tensile and compressive testing of springs, medium version from 50 N up to 500 N

Features

- Spring tester for tension and compression tests
- Measuring device integrated in housing
- **Integrated thermal printer**
- **Digital length measuring unit:**
 - Manual zero adjustment possible
 - Pre-length can be set manually
 - Readout: 0,01 mm
- **10 memories** to print out the results or to calculate average values
- **Measuring with tolerance range (limit-setting function):** Upper and lower limiting can be programmed individually, in pull and push direction. The process is supported by an audible and visual signal.
- **Peak load display** (peak hold)
- **Selectable measuring units:** kg, lbf, N

Technical data

- Precision: 0,5 % of [Max]
- Stroke length: 100 mm
- Maximum test object length: 100 mm
- Overall dimensions W×D×H 300×235×620 mm

STANDARD


































OPTION



Model	Measuring range [Max] N	Readout [d] N	Net weight kg	Option Factory calibration certificates compression	
				KERN	
SAUTER					
SD 50N100.	50	0,01	21	961-2610	
SD 100N100.	100	0,02	21	961-2610	
SD 200N100.	200	0,05	21	961-2610	
SD 300N100.*	300	0,1	21	961-2610	
SD 500N100.	500	0,1	21	961-2610	

*** ONLY WHILE STOCKS LAST!**

 Adjusting program (CAL): For quick setting of the balance's accuracy. External adjusting weight required.	 Control outputs (optocoupler, digital I/O): to connect relays, signal lamps, valves, etc.	 Rechargeable battery pack: rechargeable set.
 Calibration block: standard for adjusting or correcting the measuring device.	 Analogue interface: to connect a suitable peripheral device for analogue processing of the measurements.	 Mains adapter: 230V/50Hz in standard version for EU. On request GB, AUS or USA version available.
 Peak hold function: capturing a peak value within a measuring process.	 Statistics: using the saved values, the device calculates statistical data, such as average value, standard deviation etc.	 Power supply: Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.
 Scan mode: continuous capture and display of measurements.	 PC Software: to transfer the measurements from the device to a PC.	 Motorised drive: The mechanical movement is carried out by an electric motor.
 Push and Pull: the measuring device can capture tension and compression forces.	 Printer: a printer can be connected to the device to print out the measurements.	 Motorised drive: The mechanical movement is carried out by a synchronous motor (stepper).
 Length measurement: captures the geometric dimensions of a test object or the movement during a test process.	 GLP/ISO record keeping: of measurements with date, time and serial number. Only with SAUTER printers.	 Fast-Move: the total length of travel can be covered by a single lever movement.
 Focus function: increases the measuring accuracy of a device within a defined measuring range.	 Measuring units: Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.	 DAkkS calibration possible: The time required for DAkkS calibration is shown in days in the pictogram.
 Internal memory: to save measurements in the device memory.	 Measuring with tolerance range (limit-setting function): Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model	 Factory calibration: The time required for factory calibration is specified in the pictogram.
 Data interface RS-232: bidirectional, for connection of printer and PC.	 ZERO: Resets the display to "0".	 Package shipment: The time required for internal shipping preparations is shown in days in the pictogram.
 Data interface USB: To connect the balance to a printer, PC or other peripheral devices.	 Battery operation: Ready for battery operation. The battery type is specified for each device.	 Pallet shipment: The time required for internal shipping preparations is shown in days in the pictogram.
 Data interface Infrared: To transfer data from the balance to a printer, PC or other peripheral devices.		

Your SAUTER specialist dealer: